

Metropolitan Water Reclamation District of Greater Chicago – 100 East Erie Street Chicago, Illinois 60611-2803 312-751-5600

HANOVER PARK WATER RECLAMATION PLANT FISCHER FARM MONITORING REPORT FOR FOURTH QUARTER 2018

Monitoring and Research Department Edward W. Podczerwinski, Director

March 2019



BOARD OF COMMISSIONERS Kari K. Steele President Barbara J. McGowan Vice President Frank Avila Chairman of Finance Cameron Davis Kimberly Du Buclet Marcelino Garcia Josina Morita Debra Shore Mariyana T. Spyropoulos

Metropolitan Water Reclamation District of Greater Chicago

CECIL LUE-HING RESEARCH AND DEVELOPMENT COMPLEX 6001 WEST PERSHING ROAD CICERO, ILLINOIS 60804-4112

Edward W. Podczerwinski, P.E. Director of Monitoring and Research

February 26, 2019

Mr. Roger Callaway Illinois Environmental Protection Agency Bureau of Water DWPC Compliance Section #19 1021 North Grand Avenue East P.O. Box 19276 Springfield, Illinois 62794-9274

Dear Mr. Callaway:

Subject: Hanover Park Water Reclamation Plant - Illinois Environmental Protection Agency Permit No. 2016-SC-61315, Monitoring Report for October, November, and December 2018

The attached tables contain the monitoring data for the Hanover Park Water Reclamation Plant (WRP) Fischer Farm site for October, November, and December 2018 as required by Illinois Environmental Protection Agency (IEPA) Operating Permit No. 2016-SC-61315. Analytical data for well water samples collected during the quarter are presented in <u>Table 1</u>.

Drainage water (combined surface and subsurface) returned to the Hanover Park WRP from the farm fields was sampled in October, November, and December 2018, and data for these samples are presented in <u>Table 2</u>. The volumes of drainage water returned to the WRP during the second quarter were estimated as 7.5, 2.0, and 3.6 million gallons in October, November, and December, respectively. No lagoon supernatant or liquid biosolids were applied to Fischer Farm fields in October, November, or December. Field and water monitoring locations are presented in Figure 1.

An investigation of Well 7 is ongoing to help determine the reason for high ammonia (NH₃-N) levels observed in the well. Three supplemental monitoring wells were installed in July 2017 to monitor groundwater and determine the source of NH₃-N.

The data reported are as follows:

Table 1Analysis of Water From Monitoring Wells W-3, W-5, W-6, W-7, and
W-8 at the Hanover Park Fischer Farm Site Sampled on November 6,
2018.

Mr. Roger Callaway

- Subject: Hanover Park Water Reclamation Plant Illinois Environmental Protection Agency Permit No. 2016-SC-61315, Monitoring Report for October, November, and December 2018
- Table 2Analysis of Combined Surface and Subsurface Drainage From the FischerFarm Site Returned to the Hanover Park Water Reclamation Plant During
October, November, and December 2018.
- Figure 1 Map of Fields and Wells at the Hanover Park Fischer Farm Site of the Metropolitan Water Reclamation District of Greater Chicago.

Very truly yours,

Albert E. Cox

Environmental Monitoring and Research Manager Monitoring and Research Department

AC:DB:cm Attachments cc/att: Mr. J. Patel, Manager, IEPA – Des Plaines Mr. J. Colletti, USEPA, Region 5 Mr. P. Kuefler, USEPA, Region 5 Mr. J. Chavich Dr. H. Zhang Dr. G. Tian Dr. D. Brose

Parameter		Monitoring Well No.					
	Unit	W-3	W-5	W-6	W-7	W-8	
рН		7.5	7.8	7.8	7.8	8.2	
EC	mS m ⁻¹	97	74	76	99	60	
Cl-	mg L ⁻¹	14	17	22	41	9.0	
SO4 ²⁻	"	163	99	118	126	66	
Alkalinity as CaCO ₃	**	416	313	301	380	279	
TKN	**	<1.0	<1.0	<1.0	30	<1.0	
NH3-N	**	< 0.50	< 0.50	< 0.50	31	0.52	
NO ₂ +NO ₃ -N	н	< 0.25	< 0.25	< 0.25	<0.25	< 0.25	
Total P	**	< 0.10	< 0.10	0.144	0.46	< 0.10	
Cd	11	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	
Cr	н	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	
Cu	н	0.001	< 0.001	0.001	0.001	< 0.001	
Fe	**	0.157	NRR ¹	0.651	2.59	0.340	
Mn	**	0.040	NRR	0.012	0.067	0.015	
Ni	11	< 0.001	< 0.001	< 0.001	0.001	< 0.001	
Zn		< 0.005	< 0.005	< 0.005	0.34	< 0.005	

TABLE 1: ANALYSIS OF WATER FROM MONITORING WELLS W-3, W-5, W-6, W-7, AND W-8 AT THE HANOVER PARK FISCHER FARM SITE SAMPLED ON NOVEMBER 6, 2018


¹NRR=no reportable results. Sample was re-digested and analyzed, but results could not be quantified, likely due to matrix interference.

TABLE 2: ANALYSIS OF COMBINED SURFACE AND SUBSURFACE DRAINAGE FROM THE FISCHER FARM SITE RETURNED TO THE HANOVER PARK WATER RECLAMATION PLANT DURING OCTOBER, NOVEMBER, AND DECEMBER 2018

Date ¹	Sump	NH3-N	TSS ²	BOD ₅	
		mg L ⁻¹			
10/16/2018	East	12	10	3.0	
10/16/2018	West	2.6	8.0	8.0	
10/23/2018	East	33	13	11	
10/23/2018	West	0.77	4.0	2.0	
11/06/2018	East	5.2	11	6.0	
11/06/2018	West	3.1	21	9.0	
11/20/2018	East	0.65	12	4.0	
11/20/2018	West	28	5.8	8.0	
12/11/2018	East	9.8	11	5.0	
12/11/2018	West	<0.50	5.0	<2.0	

¹Pump houses were inaccessible for the second sampling in December due to weather. ²Total suspended solids.

FIGURE 1: MAP OF FIELDS AND WELLS AT THE HANOVER PARK FISCHER FARM SITE OF THE METROPOLITAN WATER RECLAMATION DISTRICT OF GREATER CHICAGO





BOARD OF COMMISSIONERS Kari K. Steele President Barbara J. McGowan Vice President Frank Avila Chairman of Finance Cameron Davis Kimberly Du Buclet Marcelino Garcia Josina Morita Debra Shore Mariyana T. Spyropoulos

Metropolitan Water Reclamation District of Greater Chicago

CECIL LUE-HING RESEARCH AND DEVELOPMENT COMPLEX 6001 WEST PERSHING ROAD CICERO, ILLINOIS 60804-4112

Edward W. Podczerwinski, P.E. Director of Monitoring and Research

February 26, 2019

Mr. Roger Callaway Illinois Environmental Protection Agency Bureau of Water DWPC Compliance Section #19 1021 North Grand Avenue East P.O. Box 19276 Springfield, Illinois 62794-9274

Dear Mr. Callaway:

Subject: Hanover Park Water Reclamation Plant - Illinois Environmental Protection Agency Permit No. 2016-SC-61315, Monitoring Report for October, November, and December 2018

The attached tables contain the monitoring data for the Hanover Park Water Reclamation Plant (WRP) Fischer Farm site for October, November, and December 2018 as required by Illinois Environmental Protection Agency (IEPA) Operating Permit No. 2016-SC-61315. Analytical data for well water samples collected during the quarter are presented in <u>Table 1</u>.

Drainage water (combined surface and subsurface) returned to the Hanover Park WRP from the farm fields was sampled in October, November, and December 2018, and data for these samples are presented in <u>Table 2</u>. The volumes of drainage water returned to the WRP during the second quarter were estimated as 7.5, 2.0, and 3.6 million gallons in October, November, and December, respectively. No lagoon supernatant or liquid biosolids were applied to Fischer Farm fields in October, November, or December. Field and water monitoring locations are presented in Figure 1.

An investigation of Well 7 is ongoing to help determine the reason for high ammonia (NH₃-N) levels observed in the well. Three supplemental monitoring wells were installed in July 2017 to monitor groundwater and determine the source of NH₃-N.

The data reported are as follows:

Table 1Analysis of Water From Monitoring Wells W-3, W-5, W-6, W-7, and
W-8 at the Hanover Park Fischer Farm Site Sampled on November 6,
2018.

Mr. Roger Callaway

- Subject: Hanover Park Water Reclamation Plant Illinois Environmental Protection Agency Permit No. 2016-SC-61315, Monitoring Report for October, November, and December 2018
- Table 2Analysis of Combined Surface and Subsurface Drainage From the FischerFarm Site Returned to the Hanover Park Water Reclamation Plant During
October, November, and December 2018.
- Figure 1 Map of Fields and Wells at the Hanover Park Fischer Farm Site of the Metropolitan Water Reclamation District of Greater Chicago.

Very truly yours,

Albert E. Cox

Environmental Monitoring and Research Manager Monitoring and Research Department

AC:DB:cm Attachments cc/att: Mr. J. Patel, Manager, IEPA – Des Plaines Mr. J. Colletti, USEPA, Region 5 Mr. P. Kuefler, USEPA, Region 5 Mr. J. Chavich Dr. H. Zhang Dr. G. Tian Dr. D. Brose

Parameter		Monitoring Well No.					
	Unit	W-3	W-5	W-6	W-7	W-8	
рН		7.5	7.8	7.8	7.8	8.2	
EC	mS m ⁻¹	97	74	76	99	60	
Cl-	mg L ⁻¹	14	17	22	41	9.0	
SO4 ²⁻	"	163	99	118	126	66	
Alkalinity as CaCO ₃	**	416	313	301	380	279	
TKN	**	<1.0	<1.0	<1.0	30	<1.0	
NH3-N	**	< 0.50	< 0.50	< 0.50	31	0.52	
NO ₂ +NO ₃ -N	н	< 0.25	< 0.25	< 0.25	<0.25	< 0.25	
Total P	**	< 0.10	< 0.10	0.144	0.46	< 0.10	
Cd	11	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	
Cr	н	< 0.002	< 0.002	< 0.002	< 0.002	< 0.002	
Cu	н	0.001	< 0.001	0.001	0.001	< 0.001	
Fe	**	0.157	NRR ¹	0.651	2.59	0.340	
Mn	**	0.040	NRR	0.012	0.067	0.015	
Ni	11	< 0.001	< 0.001	< 0.001	0.001	< 0.001	
Zn		< 0.005	< 0.005	< 0.005	0.34	< 0.005	

TABLE 1: ANALYSIS OF WATER FROM MONITORING WELLS W-3, W-5, W-6, W-7, AND W-8 AT THE HANOVER PARK FISCHER FARM SITE SAMPLED ON NOVEMBER 6, 2018

¹NRR=no reportable results. Sample was re-digested and analyzed, but results could not be quantified, likely due to matrix interference.

TABLE 2: ANALYSIS OF COMBINED SURFACE AND SUBSURFACE DRAINAGE FROM THE FISCHER FARM SITE RETURNED TO THE HANOVER PARK WATER RECLAMATION PLANT DURING OCTOBER, NOVEMBER, AND DECEMBER 2018

Date ¹	Sump	NH3-N	TSS ²	BOD ₅	
		mg L ⁻¹			
10/16/2018	East	12	10	3.0	
10/16/2018	West	2.6	8.0	8.0	
10/23/2018	East	33	13	11	
10/23/2018	West	0.77	4.0	2.0	
11/06/2018	East	5.2	11	6.0	
11/06/2018	West	3.1	21	9.0	
11/20/2018	East	0.65	12	4.0	
11/20/2018	West	28	5.8	8.0	
12/11/2018	East	9.8	11	5.0	
12/11/2018	West	<0.50	5.0	<2.0	

¹Pump houses were inaccessible for the second sampling in December due to weather. ²Total suspended solids.

FIGURE 1: MAP OF FIELDS AND WELLS AT THE HANOVER PARK FISCHER FARM SITE OF THE METROPOLITAN WATER RECLAMATION DISTRICT OF GREATER CHICAGO

