



 Metropolitan Water Reclamation District of Greater Chicago

 CECIL LUE-HING RESEARCH AND DEVELOPMENT COMPLEX

 6001 WEST PERSHING ROAD
 CICERO, ILLINOIS

 60804-4112

Edward W. Podczerwinski, P.E. Director of Monitoring and Research

July 30, 2020

Mr. Roger Calloway Illinois Environmental Protection Agency Bureau of Water DWPC Compliance Section #19 1021 North Grand Avenue East P.O. Box 19276 Springfield, Illinois 62794-9274

Dear Mr. Callaway:

Subject: Hanover Park Water Reclamation Plant - Illinois Environmental Protection Agency Permit No. 2016-SC-61315, Monitoring Report for April, May, and June 2020

The attached tables contain the monitoring data for the Hanover Park Water Reclamation Plant (WRP) Fischer Farm site for April, May, and June 2020, as required by Illinois Environmental Protection Agency Operating Permit No. 2016-SC-61315.

Analytical data for well water samples collected during the quarter are presented in <u>Table 1</u>. Drainage water (combined surface and subsurface) returned to the Hanover Park WRP from the farm fields was sampled in April, May, and June 2020, and data for these samples are presented in <u>Table 2</u>. The volumes of drainage water returned to the WRP during the first quarter were estimated at 24.2, 47.7, and 22.6 million gallons in April, May, and June, respectively. The analytical data for lagoon supernatant applied to Fischer Farm fields in April, May, and June are presented in <u>Table 3</u>. The volume of lagoon supernatant, and the associated dry weight of biosolids applied, are shown in <u>Table 4</u>. Field and water monitoring locations are presented in <u>Figure 1</u>.

Based on the investigation of the high levels of NH<sub>3</sub>-N in Well 7, it appears that the source of these high levels is seepage from adjacent lagoons and subsurface drainage associated with supernatant application, both of which have high NH<sub>3</sub>-N levels. Management practices are being implemented to reduce the loading in adjacent lagoons and application of supernatant in fields to confirm that these are the sources of high NH<sub>3</sub>-N in Well 7.

The data reported are as follows:

Table 1Analysis of Water From Monitoring Wells W-3, W-5, W-6, W-7, and<br/>W-8 at the Hanover Park Fischer Farm Site Sampled on June 9, 2020.

BOARD OF COMMISSIONERS Kari K. Steele President Barbara J. McGowan Vice President Frank Avila Chairman of Finance Cameron Davis Kimberly Du Buclet Marcelino Garcia Josina Morita Debra Shore Mariyana T. Spyropoulos Mr. Roger Callaway

- Subject: Hanover Park Water Reclamation Plant Illinois Environmental Protection Agency Permit No. 2016-SC-61315, Monitoring Report for April, May, and June 2020
- Table 2Analysis of Combined Surface and Subsurface Drainage From the FischerFarm Site Returned to the Hanover Park Water Reclamation Plant During<br/>April, May, and June 2020.
- Table 3Analysis of Lagoon Supernatant Applied to Fields at the Hanover ParkFischer Farm Site During April, May, and June 2020.
- Table 4Volumes and Dry Weights of Lagoon Supernatant Applied to FieldsDuring April, May, and June 2020 at the Hanover Park Fischer Farm Site.
- Figure 1 Map of Fields and Wells at the Hanover Park Fischer Farm Site of the Metropolitan Water Reclamation District of Greater Chicago.

Very truly yours,

Albert as

Albert E. Cox Environmental Monitoring and Research Manager Monitoring and Research Department

AC:BM:cm Attachments cc/att: Mr. J. Patel, Manager, IEPA – Des Plaines Mr. J. Colletti, USEPA, Region 5 Mr. P. Kuefler, USEPA, Region 5 Mr. J. Chavich Dr. H. Zhang Metropolitan Water Reclamation District of Greater Chicago – 100 East Erie Street Chicago, Illinois 60611-2803 312-751-5600

# HANOVER PARK WATER RECLAMATION PLANT FISCHER FARM MONITORING REPORT FOR SECOND QUARTER 2020

Monitoring and Research Department Edward W. Podczerwinski, Director

July 2020

		Monitoring Well No.				
Parameter	Unit	W-3	W-5	W-6	W-7	W-8
$pH^1$		7.6	7.6	7.6	7.3	7.9
EC	$mS m^{-1}$	75	74	70	142	62
Cl	mg L <sup>-1</sup>	9.5	19	21	32	10
<b>SO</b> <sub>4</sub> <sup>2-</sup>	"	77	102	116	241	76
Alkalinity as CaCO <sub>3</sub>	"	364	308	295	592	283
TKN	"	<1.0	<1.0	<1.0	NRR <sup>2</sup>	<1.0
NH <sub>3</sub> -N	"	< 0.30	0.31	< 0.30	48	0.42
$NO_2^-+NO_3^N$	"	< 0.25	< 0.25	< 0.25	< 0.25	< 0.25
Total P	"	< 0.15	< 0.15	< 0.15	1.79	< 0.15
Cd	"	< 0.001	< 0.001	< 0.001	0.002	< 0.001
Cr	"	< 0.002	< 0.002	< 0.002	0.017	< 0.002
Cu	"	0.004	0.002	0.002	0.023	0.002
Fe	"	3.62	2.52	1.54	14.8	0.973
Mn	"	0.27	0.022	0.031	0.37	0.025
Ni	"	< 0.001	< 0.001	< 0.001	0.023	< 0.001
Zn	"	0.038	< 0.005	< 0.005	0.24	< 0.005

## TABLE 1: ANALYSIS OF WATER FROM MONITORING WELLS W-3, W-5, W-6, W-7, AND W-8 AT THE HANOVER PARK FISCHER FARM SITE SAMPLED ON JUNE 9, 2020

<sup>1</sup>pH was measured beyond 15 minutes holding time.
 <sup>2</sup>No reportable result. Analysis canceled because NH<sub>3</sub>-N was greater than TKN. The sample could not be rerun for TKN due to exceedance of the holding time.

#### TABLE 2: ANALYSIS OF COMBINED SURFACE AND SUBSURFACE DRAINAGE FROM THE FISCHER FARM SITE RETURNED TO THE HANOVER PARK WATER RECLAMATION PLANT DURING APRIL, MAY, AND JUNE 2020

Date <sup>1</sup>	Sump	NH <sub>3</sub> -N	TSS <sup>1</sup>	BOD <sub>5</sub>
			mg L <sup>-1</sup>	
04/14/2020	East	9.0	6	NRR <sup>2</sup>
04/14/2020	West	14	7	$NRR^2$
04/28/2020	East	7.2	15	9
04/28/2020	West	16	17	11
05/12/2020	East	178	43	60
05/12/2020	West	22	18	22
05/26/2020	East	$ND^3$	30	ND
05/26/2020	West	ND	6	ND
06/09/2020	East	2.4	10	6
06/09/2020	West	3.5	31	12
06/25/2020	East	4.1	7	5
06/25/2020	West	2.4	5	7

<sup>1</sup>Total suspended solids.

<sup>2</sup>No reportable result. Analysis canceled because laboratory control sample result was outside of the acceptable range. The sample could not be rerun for BOD<sub>5</sub> due to exceedance of the holding time. <sup>3</sup>No data. Analysis canceled because storage temperature exceeded acceptable range.

Constituent	Unit	April	May	June
pH <sup>1</sup>		8.0	7.9	8.0
1	0/			
Total Solids	%	0.15	0.13	0.12
Total Volatile Solids	"	59.9	62.6	51.6
Volatile Acids	mg L <sup>-1</sup>	$ND^2$	ND	<5.0
TKN	"	596	592	480
NH <sub>3</sub> -N	"	549	549	460
Total P	"	60	54	46
Cd	"	< 0.001	< 0.001	< 0.001
Cr	"	0.004	0.002	< 0.002
Cu	"	0.236	0.196	0.103
Mn	"	0.532	0.468	0.359
Ni	"	0.022	0.019	0.016
Pb	"	0.006	0.005	0.002
Zn	"	0.388	0.338	0.145

## TABLE 3: ANALYSIS OF LAGOON SUPERNATANT APPLIED TO FIELDS AT THE HANOVER PARK FISCHER FARM SITE DURING APRIL, MAY, AND JUNE 2020

<sup>1</sup>pH was measured beyond 15 minutes holding time. <sup>2</sup>No data. Analysis was canceled by the analytical lab due to staffing limitations associated with the COVID-19 pandemic.

## TABLE 4: VOLUMES AND DRY WEIGHTS OF LAGOON SUPERNATANT APPLIED TO FIELDS DURING APRIL, MAY, AND JUNE 2020 AT THE HANOVER PARK FISCHER FARM SITE

Field	Date	Biosolids Type	Volume (Gallons)	Dry Weight (Tons)
5	04/02/20	Supernatant	160,000	1.07
6	04/02/20	Supernatant	160,000	1.07
1	04/03/20	Supernatant	155,000	1.04
4	04/03/20	Supernatant	155,000	1.04
1	04/09/20	Supernatant	140,000	0.82
4	04/09/20	Supernatant	140,000	0.82
5	04/10/20	Supernatant	145,000	0.91
6	04/10/20	Supernatant	145,000	0.91
1	04/14/20	Supernatant	95,000	0.56
4	04/14/20	Supernatant	95,000	0.56
1	04/22/20	Supernatant	150,000	0.94
4	04/22/20	Supernatant	150,000	0.94
5	04/23/20	Supernatant	120,000	0.80
6	04/23/20	Supernatant	120,000	0.80
5	04/28/20	Supernatant	95,000	0.60
6	04/28/20	Supernatant	95,000	0.60
1	05/07/20	Supernatant	135,000	0.79
4	05/07/20	Supernatant	135,000	0.79
5	05/11/20	Supernatant	170,000	0.99
6	05/11/20	Supernatant	170,000	0.99
1	05/12/20	Supernatant	145,000	0.85
4	05/12/20	Supernatant	145,000	0.85
1	05/18/20	Supernatant	97,500	0.45
4	05/18/20	Supernatant	97,500	0.45
5	05/18/20	Supernatant	97,500	0.45
6	05/18/20	Supernatant	97,500	0.45
1	05/19/20	Supernatant	82,500	0.35
4	05/19/20	Supernatant	82,500	0.35
5	05/19/20	Supernatant	82,500	0.35
6	05/19/20	Supernatant	82,500	0.35
5	05/20/20	Supernatant	115,000	0.53
6	05/20/20	Supernatant	115,000	0.53
1	06/04/20	Supernatant	150,000	0.75
4	06/04/20	Supernatant	150,000	0.75
Total			4,270,000	$24.41^{1}$

<sup>1</sup>Difference between sum of individual dry weights (24.50 dry tons) and reported total (24.41 dry tons) is due to rounding.

#### FIGURE 1 MAP OF FIELDS AND WELLS AT THE HANOVER PARK FISCHER FARM SITE OF THE METROPOLITAN WATER RECLAMATION DISTRICT OF GREATER CHICAGO

